

Settop M1 - New Firmware Version

Barcelona, September 2020

New Firmware v3.0.0.2

Introduction

These release notes describe the latest improvements made to the Settop M1. A new version of Settop M1 firmware is now available. The new version is identified as version 3.0.0.2.

Before you perform a firmware upgrade, please make a record of your existing Settop M1 configuration. This includes the download of your current Settop M1 project file as well as we recommend documenting your round scheduler and connection settings.

Prerequisites

- This new version of firmware can only be installed on Settop M1 units which have firmware version 2.3.1.1 or higher. For more information on the versions, please also see the upgrade procedure further below.
- Settop M1 Battery must be fully charged.

Firmware v3.0.0.2

New Features and changes

- Fixed issue when blank user and password fields are used in modem settings
- AT&T reconnection settings

Previous Firmware Versions

Firmware v3.0.0.1

New Features and changes

- Visualization issues when using Google Chrome browser
- Special language character handling in file or project names
- Initial ISTConnect registration of a new unit when using a newly created user
- Update of project file related to new tracking feature (last known position)

Firmware v3.0.0.0

New Features and changes

- New Web User Interface
- Trimble Internal Camera support
- Reset Password feature
- Last Known Position feature
- Multiple Set of Rounds feature
- Remote access and control Devices feature
- Reset Reference Circle with FineLock LR
- Minor fixes

NOTE: After updating the SettopM1, it is necessary to refresh the cache memory by pressing *Shift+F5*

Update Procedure

- The upgrade procedure from version 2.3.0.0 to the new version 3.0.0.2 requires an upgrade to version 2.3.1.1 in the first step. This means due to this intermediate step you must run the upgrade procedure twice.
- The Settop M1 must not be disconnected while updating.
- The installation packet size is 30.4Mb and is automatically downloaded during the upgrade. The upgrade time depends on your internet speed.

The Settop M1 firmware version can be updated to the latest version by following the steps below.

1. Login in to the webUI of your Settop M1 device.
2. Find the “System” button and click on it.
3. Click the “>” to go to the second screen of the System configuration page.
4. Find the “Update” button and click on it.
5. Click the “Check for a new version” button.
6. Follow the instructions in the webUI to “Download Upgrade” and “Reboot” the system when appropriate.

To update a Settop M1 with a firmware version lower than 2.1.3.5 please contact with support@settopsurvey.com